





Pull up on 2x4 to put
curve in steel & then
apply down ward force
to steel